

Installer: Ram Jack Foundation Repair · Jacksonville, FL · 904.380.8488



SITUATION

One of the most common signs of foundation failure is doors that will not close, and Corey-Kerlin Funeral Homes and Crematory of Jacksonville, Florida had an especially important door to fix. Ram Jack Foundation Repair was contacted by Corey-Kerlin to resolve severe settling in the crematory cooler at their Northside location. Time was of the essence for a sensitive project such as this one, and Ram Jack has specialty brackets that can lift & support settling slabs like this.



SOLUTION

Ram Jack installed 2 2 3/8" 15' helical piles with 10" helix blades and slab brackets to support the doorway to the crematory cooler. Once the slab bracket is installed and pressure is applied, the bracket unfolds and evenly distributes force along the bottom side of the concrete slab. The piles installed were embedded to 10 and 15 feet to 3000 PSI through the existing slab, allowing almost complete recovery. In such a sensitive environment like a crematorium, it was important the repair be quick, effective and very clean.



CONCLUSION

Ram Jack's slab bracket was the perfect solution for this project, allowing work to resume the very next day. The interior folding slab bracket minimizes the size of the hole that is drilled in the existing slab. This minimally invasive process made the customer very happy. Ram Jack's team of professionals assisted with the entire repair process, and in turn allowed Corey-Kerlin Funeral Homes to return to business as usual.



STRENGTH AND STABILITY

888.332.9909

| TOLL FREE

RAMJACK.COM

| WEB



RAMJACK®